

Junior Cert Engineering Grinds – **Week 6**

Topic: Drilling & Cutting Speeds



TuitionFarm.ieTM

Education is the key to success

Junior Cert Engineering Grinds

Week 6:

Drilling & Cutting Speeds

Sound & Visual Check

“I am now talking....”

“If you cannot hear me or see my screen please say “Cannot hear/see you” on the chat.

“If some of you can’t hear me, please restart your computer and join the class again.”



Junior Cert Engineering Grinds

Week 6: Drilling & Cutting Speeds

Lesson Overview:

By the end of this lesson you should:

- Understand how the pillar drill works and how to calculate cutting speeds
- Identify each part of the pillar drill
- Define the function of each part of the pillar drill
- Know the difference between different types of holes
- Have a better understanding of the Pillar Drill, its parts, safety and uses of it



■ The Pillar Drill




Allows to drill, ream, counter-bore, countersink and tap holes

▪ The Pillar Drill



How does it work???



How does it work???




- Motor turns on and turns the back spindle (rotation)
- Belt carries the motion across to the chuck spindle
 - This causes the chuck to rotate (drill bit)
- ***Rack and Pinion Mechanism*** allows chuck to move up and down (Manual Feed Lever)




- The Pillar Drill

SAFETY!




ED 1

SENSIBLE ED THE HANDY MAN
IS READY
TO OPERATE THE DRILL




ED 2


ED IS NOT READY TO
USE THE DRILL SAFELY



Holding the Work for Drilling




Machine vice




Holding the Work for Drilling


- Ensure that your piece is even and level in the vice!!
 - How? Make sure the drill bit and material make a right angle/inverted T shape when secured.



Machine vice



Parts of Twist Drill



End View





Figure 4-13. Twist drill angles.

- Made of **HSS** (High Speed Steel)
- Bits up to **13mm** have parallel shanks, after that they are tapered
- **Parallel Shank** – **Chuck**
- **Tapered Shank** – **Taper Bore** of Spindle
- **Flutes** – Provide cutting lips, allow **swarf to escape** and allows cutting fluid to reach cutting edges.
- **Body Clearance** – **Reduces Friction** – slightly smaller than diameter of bit
- Std Drills **Point Angle = 118°**, **Lip clearance = 12°**






Normal

High helix


Low helix

Straight flute
(zero helix)



Helix angle

- **Slow Helix** – Reduced rake angle, *brass and bronze*
- **Quick/High Helix** – Increased rake angle, softer materials (*copper and aluminium*)



Used to finish holes – smoother finish


Drill Grinding

- Tools must be re-ground if the lips become blunt/chipped/land becomes worn away towards the point.
- Both lips must be at the same angle to the drill axis.



Drill Drift

- Used for removing tools (reamers/morse taper sleeves)




Strike here to remove

Most modern machines have a built-in drift




PILOT HOLE




- Smaller hole drilled 1st
- Keeps large drill bit central
- Chisel edge of drill bit does not have to do any cutting

TAPPING SIZE HOLE



- Drilled prior to cutting an internal thread
- Must be smaller than the tapping tool (.5 smaller)


CLEARANCE HOLE



- Screw passes freely through pilot hole
- Grips onto edges of pilot hole
- Head of the screw pulls the 2 pieces of material together





BLIND HOLE



- Does not go all the way through a part
- Can be tapped to allow a screw to be used without a nut


COUNTERSINKING HOLES



- Enlarging the mouths of the holes to accommodate the heads of csk head screws and rivets.
- Point angles of : 60°/90°
- A twist drill can be used, but the point angle must be ground to the required angle.




COUNTERBORING HOLES



- Enlarging the top of previously drilled hole to accommodate flathead/cheesehead screws.
- Counterboring bit has a pilot on the end to guide it straight into the existing hole.

SPOT FACING



- Machining of rough/uneven surfaces surrounding holes – provide a flat seating.

CUTTING FLUIDS

Coolants/cutting lubricants

- Why are they used??
 - Cutting tool lasts longer
 - Machining can be carried out at a greater speed
 - Better surface finish
 - Keeps everything cool
 - Reduces friction



SPINDLE SPEED

- REVOLUTIONS PER MIN

- Depends on:
 - Size of the drill bit
 - Type of material being drilled
 - Softer=Higher Speed
 - HSS or HCS? HSS @ higher temp- retain hardness
 - Use of coolant



CUTTING SPEEDS

$$N = \frac{S \times 1000}{\pi \times D}$$

N = Spindle Speed in rev/min

S = Cutting Speed in metres/min

D = Diameter of drill bit

(b) A 15 mm diameter bar is to be turned on the lathe. The material has a surface cutting speed of 126 m/min. Using the given formula, calculate the speed in RPM. (Take π as 3)

$$N = \frac{S \times 1000}{\pi \times D}$$



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 15mm diameter bar is to be turned on the lathe. The material has a surface cutting speed of 126m/min.
Using the given formula, calculate the speed in RPM and take π as 3.



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 15mm diameter bar is to be turned on the lathe. The material has a surface cutting speed of 126m/min.
Using the given formula, calculate the speed in RPM and take π as 3.



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 15mm diameter bar is to be turned on the lathe. The material has a surface cutting speed of 126m/min.
Using the given formula, calculate the speed in RPM and take π as 3.

$$\frac{126 \times 1000}{3 \times 15} = \frac{126000}{45} = 2800 \text{ RPM}$$



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 12mm hole is drilled in a material which has the surface cutting speed of 72m/min.
Calculate the speed in RPM and take π as 3.



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 12mm hole is drilled in a material which has the surface cutting speed of 72m/min.
Calculate the speed in RPM and take π as 3.



Using the formula below, answer the following questions. (Round up answers if a decimal place is given)

$$\frac{S \times 1000}{\pi \times D}$$

A 12mm hole is drilled in a material which has the surface cutting speed of 72m/min.
Calculate the speed in RPM and take π as 3.

$$\frac{72 \times 1000}{3 \times 12} = \frac{72000}{36} = 2000 \text{ RPM}$$




SUMMARY



The Pillar Drill







How does it work???



The Pillar Drill

SAFETY!



CUTTING FLUIDS


Coolants/cutting lubricants

- Why are they used??
- Cutting tool lasts longer
- Machining can be carried out at a greater speed
- Better surface finish
- Keeps everything cool
- Reduces friction


CUTTING SPEEDS

$$N = \frac{S \times 1000}{\pi \times D}$$


N = Spindle Speed in rev/min
 S = Cutting Speed in metres/min
 D = Diameter of drill bit




TAPPING SIZE HOLE




BLIND HOLE



CLEARANCE HOLE



PILOT HOLE



I must do some revision
I must do some revision




Question 3

20 Marks

- (a) (i) Name parts **A**, **B**, **C** and **D** of the pillar drilling machine shown.
- (ii) Name and describe a suitable mechanism used to adjust the height of part **C**.
- (iii) Identify **any two** integrated safety features on the pillar drilling machine shown.
- (iv) Name an alloy steel used to make drill bits and explain why this material is suitable for drill bits.

(10 marks)




- (b) A $\text{Ø}16$ mm hole is to be drilled in a material which has a surface cutting speed of 120 m/min. Using the given formula, calculate the speed in RPM. (Take π as 3).

$$N = \frac{S \times 1000}{\pi \times D}$$

(4 marks)

- (c) (i) Name **each** of drilled holes **X** and **Y** shown opposite.
- (ii) Describe the stages required to fully thread hole **Y** using M4 taps.


(6 marks)



Question 3

20 Marks

- (a) (i) Explain the meaning of the term *spindle speed* in relation to the drilling machine.
- (ii) Outline **any two** reasons why the spindle speed of a drilling machine may need to be changed.
- (iii) Identify the type of drilled hole shown opposite.
- (iv) Explain the purpose of the morse taper sleeve shown.



(10 marks)

Sectional View of Drilled Hole

- (b) A 15 mm diameter bar is to be turned on the lathe. The material has a surface cutting speed of 126 m/min. Using the given formula, calculate the speed in RPM. (Take π as 3)

$$N = \frac{S \times 1000}{\pi \times D}$$

(4 marks)



Morse Taper Sleeve

- (c) Select **any two** of the following and explain the difference between the terms:
- (i) Chuck Key and Allen Key;
- (ii) Drill Gauge and Feeler Gauge;
- (iii) Pilot hole and Blind hole.

(6 marks)



*Any
questions*



Next Week's
Lesson:
Junior Cert
Engineering
Grinds – **Week 7**

Topic:

Thread Cutting



TuitionFarm.ieTM

Education is the key to success